

K-4257

NPIC/CSD 548/65
27 OCTOBER 1965
PAGE 6

25X1

VINH SON COMPLEX
NORTH VIETNAM
1854N 10518E

25X1

1. PRE-STRIKE PHOTOGRAPHY OF MARCH 1963, REVEALS VINH SON COMPLEX LOCATED ON THE SONG CA (RIVER) ALONG ROUTES 7 AND 15.

2. AVAILABLE STRIKE DATA REPORTS THAT THE VINH SON AREA WAS STRUCK ON

25X1

3. POST-STRIKE PHOTOGRAPHY OF [REDACTED], REVEALS SEVERAL BOMB CRATERS WITHIN THE COMPLEX, HOWEVER, NO DAMAGE IS NOTED TO CIVILIAN HOUSING.

25X1

4. POST-STRIKE PHOTOGRAPHY OF [REDACTED]
[REDACTED] REVEALS FIFTEEN PROBABLE CIVILIAN STRUCTURES DESTROYED, AND FIVE PROBABLE CIVILIAN STRUCTURES DAMAGED. ONE LARGE BOMB CRATER IS OBSERVED IN THE CENTER OF THE COMPLEX, HOWEVER, NO DAMAGE IS NOTED TO CIVILIAN HOUSING.


25X1

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

SECRET

Approved For Release 2007/10/19 : CIA-RDP80T01471R001200120010-6



NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER
VINH SON COMPLEX
NORTH VIETNAM
18-54N 105-18E

25X1



25X1

25X1



SECRET

Approved For Release 2007/10/19 : CIA-RDP80T01471R001200120010-6